



佛山市质计中心

No: C19-WT0573E

# 检 验 报 告

## Test Report

佛山市质量计量监督检测中心  
Foshan Supervision Testing Centre of Quality and Metrology





佛山市质计中心



201819002836



CMAA(粤)资质认字162号



中国认可  
国际互认  
检测  
TESTING  
CNAS L1401

No: C19-WT0573E

# 检验报告

## Test Report

Product name: Door hinge

Entrusting unit: Hong Kong Hairong Company Limited

Manufacturer: Hong Kong Hairong Company Limited

Inspection category: Commission inspection



佛山市质量监督检测中心

检验专用章

Foshan Supervision Testing Center of Quality and Metrology

检验专用章



## Foshan Supervision Testing Centre of Quality and Metrology Test Report

Form No.: QR-CX049-01A/Ed.11.0

Page 1 of 3

Product name Model, Specification Trademark, Grade	Door hinge Glass door hinge -----	Production date or batch number	-----/-----
		Sample No.	-----
Entrusting unit	Hong Kong Hairong Company Limited	Inspection category	Commission inspection
Address of entrusting unit	Foshan City	Sample quantity/method of sample receiving	2 Pieces/Sampling
Production unit (provided by the entrusting party)	Hong Kong Hairong Company Limited	Date of sample receiving	February 25,2019
Address of production unit (provided by the entrusting party)	Foshan City	Sample received by	Pan Yi
Features and status of sample	Good	Inspection date	From February 25,2019 to March 11,2019
Inspection basis	JG/T 326-2011 Fittings of glass swing door		
Inspection conclusion	Test results as shown in the report on page 2 and 3.		
Remarks	<p style="text-align: center;">Any duplicated copy will be invalid without a red stamp specifically stamped for inspection.</p> <p style="text-align: center;">This report is only responsible for the sample. The entrusting party is responsible for the authenticity of the information provided. FQM is not responsible for its authenticity and does not assume the legal responsibility arising therefrom.</p>		

(质量) (检验)



Approved by: 任湘

Checked by: 林素美

Tested by: 龙德宇

Add: No.2, Keji West Road, Shishan, Nanhai District, Foshan, Guangdong, China

# Foshan Supervision Testing Centre of Quality and Metrology

## Test Report

No: C19-WT0573E

Form No.: QR-CX049-02/Ed.11.0

Page 2 of 3

No.	Test items	Unit	Standard requirements		Test results	Single determination
1	Open and close cycling	----	After open and close cycling 50000 times when operating at the actual bearing quality	The hinge could be rotated without severe deformation or damage	Confirmed	Pass
		mm		The change of the position of the free end of the fan in the vertical direction and the horizontal direction should not exceed 2 mm	0.71	




# Foshan Supervision Testing Centre of Quality and Metrology

## Test Report (Appendix)


No: C19-WT0573E

Form No.: QR-CX049-03/Ed.11.0

Page 3 of 3

Test Site Location (Different of This Report)	-----
Sample Description	<p>Maximum load mass (kg): 45(provided by the entrusting party);                  Substrate: Stainless steel;                  Functional positioning: No positioning function (0);                  Automatic return function: No automatic return function (W);                  Open and close cycling level: I level;                  Use environment: General environment.</p> <div style="text-align: center;">  </div>
Sampling Procedure Description	-----
Non-standard Method Description	-----
Deviation Addition Exceptions	-----
Uncertainty Description of Test Result	-----
Test Environment & Status	-----
Sub-contract Items & Subcontractor	-----
Remark	-----

(Blank below)



## 声 明

1. 报告无主检、审核、批准人签章和“检验专用章”无效。
2. 报告涂改、缺页或骑缝处未盖“检验专用章”、复印后未重新加盖红色“检验专用章”，本报告无效。未经本机构书面批准不得部分复制报告。
3. 委托检验报告仅对收到的样品负责。未经本检验机构同意，委托人不得擅自使用检验结果进行不当宣传。
4. 对检验报告有异议，请在收到报告之日起 15 天内以书面形式提出，逾期视为认同检验结果。
5. 经本检验机构签发的检验报告可以通过手机扫描报告上的二维码进行网上查询真伪。如需查询完整报告内容请致电业务联系电话 0757-88735333、88735222。

## Declaration

1. Report without signature of inspector, verifier and approver and “specific seal for test report” is invalid.
2. Report is invalid in case it is altered, incomplete pages, without across-page seal, duplicate without “specific seal for test report”. Report can not be partial copied without written approval.
3. Entrusted test report is responsible for the samples received only. Test results can not be improper propagated without written approval.
4. In case of any disagreement, applicant shall make a request in written form within 15 days on receiving the report; otherwise test result shall be accepted.
5. Test report that issued by our lab can be verified by scanning the QR code. For any enquiry about full report content, please contact 0757-88735333, 88735222.

### 狮山总部

地址A: 广东省佛山市南海区狮山镇科技西路2号 邮编(P.C):528225  
Add: No. 2, Keji West Road, Shishan, Nanhai District, Foshan, Guangdong, China  
业务电话(Tel):0757-88735333 88735222 传真(Fax): 0757-88735555

### 澜石分地点

地址B: 广东省佛山市金澜路澜石国际金属交易中心8座2层23号 邮编(P.C):528000  
Add: No. 23, 2/F., Building 8, Lanshi International Metal Trade Center, Jinlan Road, Foshan, Guangdong, China  
业务电话(Tel): 0757-83132113 83132103

### 季华西分地点

地址C: 广东省佛山市禅城区季华西路罗格工业园科汇路2号 邮编(P.C):528061  
Add: No. 2, Kehui Road, Luoge Industrial Park, Jihua West Road, Chancheng District, Foshan, Guangdong, China  
业务电话(Tel): 0757-88036822 88036959

### 里水分地点

地址D: 广东省佛山市南海区里水镇中金路2号A座首层101室 邮编(P.C):528244  
Add: Room 101, 1/F, Building A, No. 2, Zhongjin Road, Lishui, Nanhai District, Foshan, Guangdong, China

中心网址(Web): <http://www.fszjzx.com> 业务电邮(E-mail): [fszjywb@163.com](mailto:fszjywb@163.com)  
投诉电话(Tel):0757-88735110 监察举报电话(Tel): 0757-88735122

